

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
Company	Johnny Pappas Sr. Environmental Engineer				
OGM	Karl Houskeeper Environmental Scientist III				

Inspection Report

Permit Number:	C0070006			
Inspection Type:	PARTIAL			
Inspection Date:	Friday, December 05, 2003			
Start Date/Time:	12/05/2003 9:00:00 AM			
End Date/Time:	12/05/2003 12:00:00 PM			
Last Inspection:	Wednesday, November 05, 2003			

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast, ~Temp 38 Deg. F InspectionID Report Number: 116

Accepted by: pgrubaug 12/08/2003

Permitee: PLATEAU MINING CORP Operator: PLATEAU MINING CORP

Site: STAR POINT MINE

Address: 847 NW HWY 191, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
9,084.00 Total Per	mitted	✓ Federal	✓ Underground		
213.40 Total Dis	turbed	✓ State	Surface		
Phase	e l	\Box County	Loadout		
Phase	e II	✓ Fee	Processing		
Phase	III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The Star Point Refuse Mine permit was issued on November 14, 2003.

Inspector's Signature:	Date	Friday, December 05, 2003

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Friday, December 05, 2003

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070006 Inspection Type: PARTIAL

Inspection Date: Friday, December 05, 2003 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

PMC has applications into the division to:

Remove the Refuse pile and associated areas from the current permit area. Remove the Post Mining Land use area from the permit area (gas well development) upon Phase III Bond Release approval.

2. Signs and Markers

The mine ID sign was observed during the inspection. The ID sign is located to the side of the county road and at the permit boundary. The sign contained the required information. The other signs and markers observed during the inspection compiled with the coal rules.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2003 water quality information has been put into the EDI website, but has not been uploaded. Water monitoring at the mine site is current.

7. Coal Mine Waste, Refuse Piles, Impoundments

The permit for the refuse pile has been issued to Sunnyside Cogeneration Associates (SCA). The permit number is C/007/042 and became effective November 14, 2003. Plateau Mining Corporation (PMC) no longer has responsibility for this area which was previously in their permit C/007/006 for the Star Point Mine.